

# Annexure D

## BUILDING SAFETY CERTIFICATE

No. 1024/1सी०

Dated: 04-04-2026

It is certified that the existing building SJP International School ..... (name of the building or premises) at Vishunpura P.O. Bernikhaba Kaptanganj Tinich marg Dubaula Basti ..... (address) is having block(s)/Floor(s) as per details below:


Detail of Block(s) in school	Block (1)	Block (2)	Block (3)	Block (4)	Block (5)	Block (6)
No. of Floor(s) in the Block	Ground Floor 1st Floor 2nd Floor (G+2)					

The building is owned/occupied by SJP International School ..... (name of the Institution) have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of P.W.D. CD-1 Basti (Name of Department/ Govt.) on 24.03.2026 (date of inspection) in the presence of Manager J.P. Tiwari ..... (name and addresses of the Manager/Secretary or his representative) and that the building/premises is fit for occupancy for running school with effect from 24.03.2026 for a period of 05 years in accordance with rule and subject to compliance of the specific conditions as appended.

- 1.
- 2.
- 3.
- 4.

Issued on 24.03.2026 at P.W.D. CD-1 Basti by

\* Strike out whichever is not applicable. In case of block is more than six use separate sheet for detail.

  
**Executive Engineer**  
 Construction Division No.-1, P.W.D.  
 Basti  
 Name: Awadhesh Kumar  
 Designation: Executive Engg  
 Name & Address of Department/ Office: P.W.D. CD-1  
Basti